



PartsPro Cleaner RM 39

Gentle cleaning and degreasing agent effectively removes oil, grease and soot stains from metal parts and provides temporary corrosion protection.

pH 10.5
in concentrate



Properties

- Effective degreaser for high-pressure and parts cleaners
- Dissolves oil, grease and rust stains
- Protects metal parts from corrosion for short-term intermediate storage
- Gentle on materials
- Low-foam formulation
- pH value in concentrate approx. 10
- Yellowish liquid with characteristic smell
- NTA free
- Free from nitrite and halogenated hydrocarbons

Application

- High-pressure washers
- Parts cleaners

Areas

Car dealership and garage
Industry

Parts cleaning
Surface degreasing

Technical data

Container sizes	Packaging unit	Part number
20 l	1 Piece(s)	6.295-165.0
200 l	1 Piece(s)	6.295-424.0

Application

High-pressure washers

- Set the dosage and temperature on the device
- 60-80°C processing temperature.
- Clean object.
- Allow to soak.
- Contact time 1-10 minutes, depending on the degree of soiling.

Parts cleaners

- Pour the product into the parts cleaner in the appropriate dosage.
- Set the temperature and cleaning time on the device.
- 60-80°C processing temperature.
- Contact time 1-10 minutes, depending on the degree of soiling.

Directions for use

- Rinse thoroughly with hot water before additional surface treatment (painting, galvanising, etc.).
- Ensure quick drying after treatment and for dry storage.
- Proper disposal of old alkali on the part cleaning machine.

Warnings and safety recommendations according to EC Directives

- H319 Causes serious eye irritation
- P280i Wear eye/face protection.
- P305 + P351 + P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
- P337 + P313 If eye irritation persists: Get medical advice/attention.

Further information

- Dusseldorf Chamber of Crafts expert report on freedom of volatile halogen hydrocarbons
- Material Safety Data Sheet (MSDS)

Dosage and yield

Content	Cleaning method	Dosage	Contamination	Productivity
1000 ml	High-pressure washers	2 – 5 %	medium	33 m ²
1000 ml	Parts cleaners	1 – 5 %	medium	100 l