

FloorPro Tyre and Abrasion Marks Remover RM 776

Special cleaner for removing rubber abrasion marks and marks caused by forklift trucks. Even adhesive tape residues and heavy oil and soot contamination are effectively removed.

pH 13 in concentrate









Properties

- Powerful special cleaner for removing tyre and abrasion marks
- Removes rubber abrasion marks and other marks left by forklift trucks
- Dissolves even the most stubborn oil, grease, tar, soot and smoke resin contamination
- Removes wax and polymer coatings
- Effectively removes adhesive tape residues
- Can also be used for final cleaning on building sites
- NTA-free

| ١ | U | sa | ge | 0 | b. | ti | 0 | n | 9 |
|---|---|----|----|---|----|----|---|---|---|
| | | | | | | | | | |

Spray units

| ١ | Appl | ication | areas |
|---|------|---------|-------|
| | | | |

| Car dealership and garage | Floor cleaning |
|------------------------------------|----------------|
| Building Industry | Floor cleaning |
| Building cleaning | Floor cleaning |
| Industry | Floor cleaning |
| Municipal | Floor cleaning |
| Retail | Floor cleaning |
| Haulage contractors, bus operators | Floor cleaning |

Technical data

| Container sizes | Packaging unit | Part number |
|-----------------|----------------|-------------|
| 10 | 1 Piece(s) | 6.295-545.0 |
| 20 | 1 Piece(s) | 6.295-546.0 |
| 200 | 1 Piece(s) | 6.295-572.0 |



Application

Deep cleaning

- Remove coarse dirt by sweeping.
- Wet the contaminated area completely with e.g. a pump sprayer.
- Allow to soak
- Contact time 10-15 minutes, depending on the degree of soiling.
- Clean and vacuum the surface with a scrubber dryer using the 1-step method.

Instructions for use

- Test on an inconspicuous part for material compatibility.
- Do not apply to alkali-sensitive surfaces.
- Do not apply to wood, linoleum or unsealed parquet flooring.
- Do not use coloured pads (risk of colour bleeding)
- Do not let the cleaning solution dry out.
- Wear protective gloves and safety goggles when using the product.
- Ensure good ventilation.
- Use only solvent-resistant spray units.
- Store away from frost.

Warnings and safety recommendations according to EC Directives

- Danger
- H314 Causes severe skin burns and eye damage
- H290 May be corrosive to metals
- P280 Wear protective gloves/protective clothing/eye protection/face protection.
- P303 + P361 + P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].
- P305 + P351 + P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
- P310 Immediately call a POISON CENTER/doctor.
- P405 Store locked up.
- P501a Dispose of contents/container in accordance with local/regional/national/international regulations.

Further information

■ Material Safety Data Sheet (MSDS)

Dosage and vield

| Contents | Cleaning method | Dosage | Soiling | Yield |
|----------|-----------------|-------------------|---------|-------|
| 1000 ml | Deep cleaning | 40 ml/m²undiluted | heavy | 25 m² |