

Floor care for sealed parquet/laminate/cork RM 531

Optimum care and protection for sealed parquet, laminate and cork floors. Traces are removed, the care film is renewed and the floor is left with a silky shine. Notes: leave treated floors to harden for 24 hours, do not apply water, do not move furniture and do not walk on the floor wearing shoes.





Propertie

- Optimal care and protection
- Freshening
- Gives a semi-matt shine
- Polishes well

Usage ontions

- manual
- Vacuum polishers

	App	lication	areas
ı	App	IILALIUII	ai cas

Varnished parquet

Laminate floors Cork floors

Technical data

Container sizes

1 |

Packaging unit 6 Piece(s) Part number 6.295-777.0

Floor care for sealed parquet/laminate/cork RM 531, 0.011-729.0, 2024-09-02



Application

For first application

- Vacuum and damp wipe floor.
- Wash the mop out and wring until damp.
- Use 10 ml/m² of care agent and distribute uniformly in sections with the wiping
- Allow damp care film to dry fully (approx. 20-30 mins) and then polish the floor.

Application on protected floors

- Vacuum the floor.Add 30 ml/l to the wiping water, wipe floor to make it slightly damp, allow to dry and polish if necessary.

- Let treated floors dry for 24 hours.
- Do not use water.
- Do not move furniture or walk on in shoes.
- Store away from frost.

Warnings and safety recommendations according to EC Directives

■ EUH 210 Safety data sheet available on request.